2009 COMMERCIAL SCHEDULE

GENERAL INFORMATION

2009 *Subject to Change*

In all the following classes, the Very Good Quality is almost always very close to the best to be found, and very few will be found that are better. However, there will be properties worse than the Low Cost Quality, especially in retail stores, and the appraiser's judgment should be exercised or he/she should counsel with his/her immediate supervisor.

In the Retail Stores a Class 3, or metal, classification has been added due to increasing use of this type building. Metal buildings adapted to other uses will also be encountered, and the appraiser should be alert as to detect a metal building which has brick veneer, etc.

It should be stressed that when using the cost ranges that the descriptions are general and single items may apply to a higher or lower class, but may not significantly affect the cost range except to place the property in the upper or lower portion of the cost range.

SUGGESTIONS FOR ESTIMATING DEPRECIATION COMMERCIAL AND LIGHT INDUSTRIAL

PHYSICAL

Curable That which is feasible to repair. Estimate cost to

cure items which would make property saleable. This may not be necessary or may be unfeasible.

(Salvage value?).

Incurable Loss in value to "bone structure" of the improvements.

Generally estimated by an age/life ratio of incurable

items such as framing, roof structural, wiring,

foundation, etc.

FUNCTIONAL

Curable Deficiencies which could be feasible cured such as

old light fixtures, out of date plumbing fixtures, etc.

Measured by cost to cure.

Incurable Deficiencies which are unfeasible to cure such as a

misplaced bath, rooms to small, etc. Measured by

capitalized rent loss, theoretically.

ECONOMIC

Loss in value due to adverse outside influences, such as, change in character of neighborhood, undesirable uses adjacent or nearby etc. Measured by capitalized rent loss, theoretically.

2009 - EXTRA ITEMS

SUBJECT TO CHANGE

CARPORTS AND CANOPIES		DOCK HEIG		
CARPORTS	AND CANOPIES	DHT	\$1.00	
004	¢4.00	טחו	Φ1.00	
CO1	\$1.00 \$1.50	ELEVATOR		
CO2	\$1.50 \$2.00	ELVATOR	\$1.75	SA2&SB2
C03	\$2.00 \$2.50	ELV	\$2.50	SA&SB 3-6
CO4	·		\$2.50 \$1.90	UA4 UB4
CO5	\$3.00		\$1.90 \$2.60	UA5 UB5
CO6	\$3.50 \$4.00		\$2.00	0/10/0/20
CO7	\$4.00 \$4.50	Fireplace		
CO8 CO9	\$4.50 \$5.00	FIR	\$1,000	
CO9 CO10	\$5.50 \$5.50	1 117	\$1,000	
CO10	\$6.00	Pools		
CO11	\$6.50	LPL	\$5,000	
CO12	\$7.00	L: L	ψ0,000	
C013	\$7.50 \$7.50	Sprinklers		
CO14 CO15	\$8.00	SPK	\$1.50	
CO16	\$8.50	Of IC	Ψ1.00	
CO16	\$9.00	Truck Wells		
CO17	\$9.50 \$9.50	TKW	\$8.00	
CO18	\$10.00	1100	Ψ0.00	
CO20	\$10.50	Tennis Court	· e	
CO20	\$11.00	TN4	\$10,000	
CO21	\$11.50	1144	Ψ10,000	
CO23	\$12.00	Vacuums		
CO23	\$12.50	VCI	\$650	
CO25	\$13.00	Excpt WA2	\$250	
CO26	\$13.50	VC2	\$850	
CO27	\$14.00	VC3	\$1,000	
CO28	\$14.50		* . ,	
CO29	\$15.00	Brick Vener		
CO30	\$15.50	VEN	\$1.50	
CO31	\$16.00		•	
CO32	\$16.50	Concrete		
CO33	\$17.00	CPK	\$3.00	
CO34	\$17.50	-	*	
CO35	\$18.00	Asphalt		
CO36	\$18.50	APK	\$1.00	
CO37	\$19.00		,	
CO38	\$19.50	Drive Up Wir	ndow	
CO39	\$20.00	DUW .	\$15,000 ea	ach
CO40	\$.50			
7.00		Walk Up Tell	er	
		WUT	\$20,000 e	ach
DRY (CANOPIES		•	
DRC1	\$3.00			
DRC2	\$4.00			
DRC3	\$5.00			
DRC4	\$6.00			
** *	· · · · · · · · · · · · · · · · · · ·			

COMMERCIAL SCHEDULE FOR EAVE (WALL) HEIGHT ADJUSTMENT

2009

AA Auto Showroom MA Mini Warehouse

YA Warehouse/Auto Service Garage

Eave Ht	% of base cost
8ft - 13ft	92
14ft	100
15ft - 20ft	108
21ft - 25ft	121
26ft - 30ft	132
31ft - 40ft	145
41ft - 50ft	159

EA Discount Stores

EB Big Box Warehouse

LA Markets

UA Retail/Dept Stores

UB Shopping Centers

UC Drug Stores

Eave Ht	% of base cost
8ft - 11ft	95
12ft	100
13ft - 16ft	105
17ft - 24ft	119
25ft - 30ft	134
31ft - 50ft	142

^{*}Subject to Change*

FAST FOOD RESTAURANTS (GA)

2009 *Subject to Change*

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$51.03
2	Average	\$72.45
3	Good	\$83.32
4	Very Good	\$98.40

The cost per square foot for fast food restaurants include average lighting and electrical outlets and average interior finish. Very good and good restaurants typically have larger dining areas and drive-in window service.

LAUNDROMATS (HA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	55.87
2	Average	58.78
3	Good	62.56

^{*}Subject to Change*

2009 CHURCHES (XC)

QUALITY	COST - SQ.FT.	RANGE	CLASS
Marshall Value			М

^{*}Subject to Change*

SCHOOLS (XG)

2009

QUALITY	COST - SQ.FT.	RANGE	CLASS
Marshall Value			М

^{*}Subject to Change*

DRUG STORE (UC)

Quality	2009 Cost – Sq Foot	Class
Class: D Type: Low Cost	\$64.19	1
Class: D Type: Average	\$76.50	2
Class: D Type: Good	\$91.44	3
Class: D Type: Excellent	\$109.56	4

^{*}Subject to Change*

SERVICE STATIONS (WA)

Square Foot Costs

The following costs are based on median costs per square foot of complete stations, excluding equipment such as hoists and compressors, and also excluding all exterior equipment and improvements. Heating and cooling should be added from this section or section 53. Area includes office, sales, and lube areas. For masonry stations, use comparable steel building costs.

(1) CHEAP WOOD FRAME

Typically, this is an older, substandard station of wood frame and siding or stucco, with two cheap plumbing fixtures, and minimum incandescent lighting.

AREA	COST	AREA	COST	AREA	COST
300	\$30.00	500	\$24.50	800	\$20.50
400	\$26.75	600	\$22.75	1,000	\$18.50

(2) LOW COST WOOD FRAME

This is typically a station built within the Uniform Building Code, of wood frame and stucco or siding. Plumbing consists of two or three low cost fixtures.

400	\$37.75	600	\$33.00	1,000	\$27.75
500	\$35.00	800	\$30.00	1.200	\$26.75

(3) LOW COST STEEL

This is usually an older independent or local company station walls, 9' or 10' high, little or no overhang, and few built-in items. Plumbing averages four residential type fixtures.

400	\$46.50	800	\$38.00	1,200	\$33.75
600	\$41.25	1 000	\$35.75	1.400	\$32.25

(4) AVERAGE STEEL

Typically, this is the lower quality of present-day major oil company station, with 10' or 11' high painted walls, small overhangs, and five or six low cost commercial plumbing fixtures.

600	\$49.00	1,200	\$39.00	1,800	\$34.25
800	\$44.50	1,400	\$37.25	2,000	\$33.25
1,000	\$41.50	1,600	\$35.75	2,200	\$32.25

Service Stations Page 2

(5) GOOD STEEL

This is typically the average station built by major companies today, of porcelainized steel construction, 12' or 13' high, good fenestration, tiled restrooms, sectional garage doors, and generally good workmanship. Many of the ranch or suburban styled stations fit in this quality. Plumbing consists of six or seven average commercial fixtures.

AREA	COST	AREA	COST	AREA	COST
800	\$54.00	1,400	\$45.25	2,000	\$40.25
1,000 1,200	\$50.25 \$47.50	1,600 1,800	\$43.25 \$41.75	2,200 2,400	\$39.00 \$38.00

(6) EXCELLENT STEEL

This is a porcelainized steel or good brick structure, often with face brick or stone trim. It has six to eight good commercial grade plumbing fixtures with hot water heater, good fenestration and garage doors. Flat-roofed stations are usually 12' to 14' high. Workmanship is excellent and there are many built-in features.

800	\$67.75	1,400	\$56.00	2,000	\$49.50
1,000	\$62.75	1,600	\$53.50	2,200	\$48.00
1,200	\$59.00	1,800	\$51.25	2,400	\$46.50

SHOPPING CENTERS (UB)

2009

QUALITY	COST - SQ.FT.	RANGE	CLASS
	49.47		1
	60.20		2
	75.60		3
	92.00		4
Marshall Value			M

^{*}Subject to Change*

RESTAURANTS (TA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$30.94
2	Average	\$42.81
3	Good	\$56.13
4	Very Good	\$73.63

Add Sprinklers @ \$1.50 per sq.ft. Add 10% for Drive-Ins with no seating

^{*}Subject to Change*

TELEPHONE RELAY OR STITCHING STATIONS (XA) 2009

These buildings are normally on a concrete slab (with or without footings), brick bearing walls, built-up roof, vinyl asbestos tile, celotex ceiling with recessed fluorescent fixture, two bathroom fixtures, and central air and heat

QUALITY	COST - SQ.FT.	CLASS
	\$29.50	1
Marshall Value		М

^{*}Subject to Change*

POST OFFICES (XD)

2009

QUALITY	COST - SQ.FT.	RANGE	CLASS
Marshall Value			М

^{*}Subject to Change*

2009 FIRE STATIONS (XF)

QUALITY COST - SQ.FT. RANGE CLASS

Marshall Value ---- M

^{*}Subject to Change*

2009 HOSPITALS (XB)

QUALITY COST - SQ.FT. RANGE CLASS

Marshall Value ---- M

^{*}Subject to Change*

2009 THEATERS/AUDITORIUMS (XH)

QUALITY COST - SQ.FT. RANGE CLASS

М

Marshall Value ----

^{*}Subject to Change*

TELEPHONE COMPANY WORK CENTERS (XI)

2009

QUALITY COST - SQ.FT. RANGE CLASS

Marshall Value ---- M

^{*}Subject to Change*

2009 VETERINARY CLINICS (SE)

CLASS

1	LOW	\$68.33
2	FAIR	75.60
3	AVERAGE	97.06
4	GOOD	109.06

^{*}Subject to Change*

RICE DRYERS (VA) 2009

(1) Concrete \$2.50 per Barrel of Capacity

(2) Metal and Others \$2.00 per Barrel of Capacity

Subject to Change

RETAIL AND DEPARTMENT STORES (UA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$32.50
2	Average	\$41.25
3	Good	\$51.61
4	Very Good	\$58.05

Add Sprinklers @ \$1.50 per sq.ft.

Subject to Change

BARBER SHOP/BEAUTY SHOP (BA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$52.88
2	Average	\$56.48
3	Good	\$73.58

^{*}Subject to Change*

AUTO DEALERSHIPS (AA)

2009 *Subject to Change*

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$35.69
2	Average	\$36.73
3	Good	\$55.17
4	Very Good	\$80.21

Add Sprinklers @ \$1.50 per sq.ft.

Classes 1 and 2 are typical of service buildings associated with auto dealerships, auto repair shops, service companies, etc.

WAREHOUSE AND AUTO SERVICE GARAGES (YA) LIGHT INDUSTRIAL

2009

CLASS	QUALITY	COST - SQ.FT.
1	Cheap	\$15.84
2	Low Cost	\$20.08
3	Average	\$24.82
4	Good	\$31.52
5	Very Good	\$34.81
6	Good Service Centers	\$48.15
7	Very Good Service Centers	\$58.11

Add \$4.30 per sq. ft. for Dock Height Add \$2.25 per sq. ft. for Sprinklers Add \$11.00 per sq. ft. for Truck Wells

^{*}Subject to Change*

LODGES, CLUBS AND DANCE STUDIOS (IA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	45.11
2	Average	50.30
3	Average with Hardwood Dance Floor	61.79
4	Good	83.91
5	Very Good	116.52

^{*}Subject to Change*

LUMBER YARD BUILDINGS

LUMBER STORAGE (JA)

2009 - *Subject to Change*

QUALITY	COST – SQ.FT.	RANGE	CLASS
Low Cost	\$ 7.10	\$3.00 - \$ 8.00	1
Average	\$ 9.00	\$5.00 - \$10.00	2
Good	\$11.00	\$7.00 - \$12.00	3
Good	\$11.50	\$8.00 - \$13.00	4
Marshall Value			М
	MATERIAL	STORAGE (KA)	
Average	\$ 8.10	\$5.00 - \$10.00	2
Good	\$10.60	\$6.00 - \$11.00	3
Good	\$11.30	\$7.00 - \$12.00	4
Marshall Value			М

CONVENIENCE STORE AND SIMILAR BUILDINGS (FA) 2009

CLASS	QUALITY	COST - SQ.FT.
1	Metal	\$59.63
2	Stucco	\$89.38
3	Concrete Block	\$91.94
4	Brick Veneer	\$107.67
5	Good Brick or Stone	\$126.27

^{*}Subject to Change*

CAR WASH (DA)

2009

CLASS	QUALITY	COST - PER STALL
1	Low Cost	\$10,150
2	Fair	\$12,260
3	Average	\$14,670
4	Good	\$16,580
5	Automated	\$54,000

Add Dry Canopies from \$9.00 - \$18.00 per sq.ft. Add Vacuums @ \$650, \$850, \$1000 each

Subject to Change

DISCOUNT STORES (EA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$27.47
2	Average	\$35.30
3	Good	\$39.74
4	Very Good	\$51.85

Add for Sprinkler Systems @ \$1.50 per sq.ft. Truck Wells @ \$8.00 per sq.ft.

Subject to Change

BOWLING ALLEYS (CA)

2009

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$30.32
2	Average	\$40.89
3	Good	\$54.59
4	Very Good	\$58.10

Add for Sprinkler Systems @ \$2.50 per sq.ft. *Subject to Change*

BIG BOX RETAIL DISCOUNT STORES (EB)

<u>2009</u>

Quality	<u>Cost – Sq Foot</u>	<u>Class</u>
Class: D Type: Low Cost	\$27.58	1
Class: D Type: Average	\$36.66	2
Class: D Type: Good	\$48.64	3

^{*}Subject to Change*

NURSING HOMES (RA)

QUALITY	COST - SQ.FT.	CLASS
Low Cost	\$60.16	1
Average	\$78.48	2
Average	\$91.28	3
Good	\$104.00	4
Very Good	\$137.33	5
Marshall Value		М

^{*}Subject to Change*

OFFICES (SA)

2009

<u>CLASS</u>	QUALITY	COST - SQ.FT
1	Low	\$33.83
2	Fair	\$43.86
3	Average	\$46.25
4	Good	\$64.90
5	Very Good	\$77.08
6	Excellent	\$98.10

Add \$2.50 per sq.ft. for elevators

Subject to Change

GOVERNMENT OFFICES (SD)

2009

QUALITY COST - SQ.FT. RANGE CLASS

М

Marshall Value ----

SUBJECT TO CHANGE

MEDICAL OFFICES (SB)

2009

CLASS	QUALITY	COST - SQ.FT
1	Low	\$58.87
2	Fair	\$67.11
3	Average	\$77.26
4	Good	\$101.98
5	Very Good	\$122.37
6	Excellent	\$134.16

Add \$2.50 per sq.ft. for elevators

Subject to Change

BANKS (SC)

2009

CLASS	QUALITY	COST - SQ.FT
2	Average	\$90.60
3	Good	\$117.30
4	Very Good	\$140.85
5	Excellent	\$159.82
6	Drive-Up Facility	\$181.29

Add Drive-In Tellers - \$15,000 each Add Walk-Up Tellers - \$20,000 each

^{*}Subject to Change*

MOTELS (PA)

2009 - *Subject to Change*

CLASS	<u>QU</u>	<u>ALITY</u>	COST - SQ.FT.
1	Class: D	Type: Cheap	\$40.00
2	Class: D	Type: Low Cost	\$45.00
3	Class: D	Type: Fair	\$55.00
4	Class: D	Type: Average	\$65.00
5	Class: D	Type: Good	\$90.00
6	Class: D	Type Excellent	\$120.00

MINI-WAREHOUSE (MA)

2009

CLASS	QUALITY	COST - SQ.FT
1	Low	\$8.40
2	Fair	\$11.89
3	Average	\$18.10
4	Good	\$20.23
5	Very Good	\$24.23
6	Excellent	\$26.18
7	Climatized	\$30.49

SUBJECT TO CHANGE

MARKETS (LA)

2009 *Subject to Change*

CLASS	QUALITY	COST - SQ.FT.
1	Low Cost	\$43.06
2	Average	\$45.84
3	Good	\$59.83
4	Very Good	\$76.12

Add Sprinklers @ \$1.50 per sq.ft. Truck Wells @ \$8.00 per sq.ft.

MOBILE HOME PARK (NA)

2009

CLASS	QUALITY	COST (per space)
1	Cheap	\$3,300
2	Low Cost	\$5,400
3	Average	\$7,600
4	Good	\$10,800

^{*}Subject to Change*

MORTUARIES (OA)

2009

CLASS	<u>QUALITY</u>	COST - SQ.FT.
1	Low Cost	\$43.36
2	Average	\$60.31
3	Good	\$81.60
4	Very Good	\$82.79

^{*}Subject to Change*

2009 LIBRARIES (XE)

QUALITY COST - SQ.FT. RANGE CLASS

Marshall Value ---- M

^{*}Subject to Change*